

DENNEY

AEROCRAFT
COMPANY

June 10, 1991

SERVICE BULLETIN #16

SUBJECT: Great American Propellers

TO: KITFOX™ Builders with the KFM Engine & Great American Propeller

FROM: Denney Aircraft Company

A KITFOX™ builder recently reported that a section of tip, about 1" long, separated from his Great American propeller in flight. He was able to land the aircraft without damage.

Two other builders have reported that they found cracks very near the tips of their Great American propellers.

These two-bladed propellers were provided with most KFM-112 Engine Kits.

Denney Aircraft Company recommends that every builder with a Great American propeller inspect it very thoroughly before each flight, especially near the tips, for cracks or delamination.

We strongly recommend that the Great American propeller be replaced immediately with a new propeller.

The Great American Propeller Company is no longer in business, so you will have to purchase your new propeller from another supplier. We recommend that you deal with Prince Aircraft Co., 6774 Provident St., Whitehouse, Oklahoma 43571, Phone (419) 877-5557, FAX (419) 877-5557. Lonnie Prince has an excellent reputation for very high quality products, and will design and build a propeller that will suit the KITFOX™ and the KFM engine.

If you need assistance in any way, please call customer service, before returning any items to Denney Aircraft Co. Please obtain a Return Goods Authorization (RMA) number from customer service.

Nampa Airport, 100 N. Kings Rd., Nampa, Idaho 83687 • (208) 466-1711 • FAX (208) 466-7194