



SkyStar Aircraft Corporation

100 N. Kings Road • Nampa, ID 83687
Telephone: (208) 466-1711 • FAX: (208) 466-7194

SERVICE BULLETIN #19

October 26, 1992

Kodiak Reasearch, Inc.
1575 W. Commercial Blvd. #33B
Ft. Lauderdale, FL 33309

Denney Aerocraft Co.
100 N. Kings Road
Nampa, ID 83651

Re: Up dated P/N 241 783

Dear Kitfox Customer,

Kodiak Research, Inc. has informed us that there is a mandatory replacement of the drain plug that was shipped with some of its engines.

Affected engines and corresponding Serial number(s) are 3972717 -
723, 731, 724, 725, 739, 740, 745, 746, 750, 734, 735, 752, 738, 685, 704, 710, 712, 697,
713, 716, 718, 722, 751, 754, 755, 728, 737, 756, 753, 770, 773, 766, 769, 768, 812, 814,
822, 721, 711, 742, 714, 719, 816, 815, 720, 715.

Enclosed you will find the following:

2 x 241 783 - Magnetic Drain Plug for the 912 engine. (2 per engine)