



Nampa Airport • 100 N. Kings Rd. • Nampa, ID 83687 • (208) 466-1711 • FAX (208) 466-7194



SERVICE LETTER #36

DATE: August 22, 1994

SUBJECT: Cable Guides

APPLICABILITY: Series 5 Aircraft through S/N S9407xxxx; Vixens through S/N V9407xxxx

COMPLIANCE: As required

FROM: SkyStar Aircraft Product Development Department

Some Series 5 fuselage weldments have been shipped that had the aft rudder cable guides welded to the inside of the fuselage tubing instead of the outside. Inspect your fuselage to ensure that your cable guides were properly positioned. If you find that your guides were mis-located, contact Customer Service at 208-466-1711. We have developed a simple retrofit kit that allows you to install cable guides in the correct location without having to do any welding; request P/N 10435.000.