

DENNEY

**AEROCRAFT
COMPANY**

KITFOX SERVICE LETTER #4

SUBJECT: SPINNER

TO: ALL KITFOX OWNERS

FROM: DENNEY AEROCRAFT COMPANY

SPINNER: Some builders have experienced problems with their spinner. The rear bulkhead developed cracks which when left unattended caused the spinner to come off in flight. While we research the problem we recommend that all spinners be removed. The KITFOX can be flown without the spinner. While it may not be as aesthetically pleasing, it will be safer to fly without the spinner. We have not experienced any problem on the prototype with over 300 hours on it. We will keep you informed of any changes or modifications.

If you need assistance in any way, please call customer service. Before returning any items to Denney Aerocraft Co. please obtain a Return Goods Authorization (RMA) number from customer service.