



Nampa Airport • 100 N. Kings Rd. • Nampa, ID 83687 • (208) 466-1711 • FAX (208) 466-7194



## SERVICE LETTER #43

**DATE:** November 28, 1994

**SUBJECT:** Series 5 Speedster Rudder

**APPLICABILITY:** All Series 5 Speedsters

**COMPLIANCE:** As required

**FROM:** SkyStar Aircraft Engineering Department

---

Due to a conflict in the control system between the rudder intercostals and the elevator, the rudder travel on all Series 5 Speedsters must be limited to 25° in each direction and not 30°, as given in the assembly instructions.

If you have already set the travel to 30°, please contact our Customer Service Department at 208-466-1711 to retrofit your aircraft in accordance with the current limitations.