

**DENNEY**

**AEROCRAFT  
COMPANY**

July 14, 1987

**SERVICE BULLETIN #1**

**SUBJECT: E-72 PLASTIC SPINNER RECALL**

**TO: Kitfox Owners with 3-Blade Prop and Plastic Spinner**

**FROM: DENNEY AEROCRAFT COMPANY**

The corrective actions that we have taken to eliminate the problem of the plastic snap on spinner coming off in flight have not worked.

Please send your E-72 Plastic Spinner back to Denney Aircraft Company as soon as possible.

Upon receipt of your plastic spinner, we will send out a new E-31 Aluminium Spinner and E-33 Bulkhead for replacement.

Do Not, REPEAT Do Not fly or run the aircraft with the E-72 Plastic Spinner installed.

***If you need assistance in any way, please call customer service. Before returning any items to Denney Aircraft Co. please obtain a Return Goods Authorization (RMA) number from customer service.***