

DENNEY
AEROCRAFT
COMPANY

August 20, 1987

SERVICE LETTER #11

SUBJECT: WING TANK RECALL

TO: KITFOX OWNERS WITH WING TANKS RECEIVED BEFORE MARCH 23, 1987

FROM: DENNEY AEROCRAFT COMPANY

If you have a wing tank that you received before March 23, 1987, there is the possibility that it may develop a leak in the bottom welded edge. We have found that after a number of hours of use, the flexing of the bottom skin may cause the weld to crack.

Send your wing tank back to Denney Aircraft and we will correct it at NO CHARGE.

If your tank is already installed, we recommend that you remove it and send it back.

If you need assistance in any way, please call customer service. Before returning any items to Denney Aircraft Co. please obtain a Return Goods Authorization (RMA) number from customer service.