



## SERVICE LETTER # 26


**DATE:** February 10, 1994

**SUBJECT:** Nose Gear Piston - P/N 35020.000

**TO:** Vixen S/N ECV-001 through LCV-023

**FROM:** SkyStar Aircraft, Engineering Division

---



**Figure A**

It has come to our attention that a few Vixen customers received a Nose Gear Piston (P/N 35020.000) without a welded boss on both ends. Please inspect the Nose Gear Piston to verify that you have a welded boss on both ends per Figure A. If the welded boss is missing, please call our Customer Service Department at (208) 466-1711 for a RMA (Return Merchandise Authorization) number. For domestic customers, return the Nose Gear Piston back to SkyStar and we will ship you a replacement. International customers will be shipped a new P/N 35020.000 Nose Gear Piston - no return is necessary.

If you have any questions, please do not hesitate to call our Customer Service Department.