





Caldwell Industrial Airport · 3901 Aviation Way · Caldwell, ID 83605 · (208) 454-2444 · FAX (208) 454-6464

SERVICE LETTER #55

DATE:

August 6, 1999

SUBJECT:

Weight and Balance

APPLICABILITY:

Vixen and Voyager Aircraft

COMPLIANCE:

Recommended

FROM:

SkyStar Aircraft Product Development

A Kitfox Vixen customer recently informed us of a possible aft CG problem encountered during the initial weight and balance calculations after weighing his aircraft for the first time. The aircraft is a Vixen (1400 lb gross weight) using a 912 UL Rotax engine and a ground adjustable, wood GSC prop. While SkyStar has not experienced any aft CG loading problems on our Demo planes or had other builders call with similar problems, we would like to gather more information from our builders. SkyStar would greatly appreciate feed back from our builders on their weight and balance findings (all engine types). Please fill out the attached Survey (even if you have not completed a weight and balance yet) to help us in determining if this is an isolated case or if in fact there might be others with similar conditions.

Product Development

VIXEN WEIGHT AND BALANCE SURVEY

| Owner: | Phone Number: |
|---|--|
| Aircraft Serial Number: | (important) |
| Engine Type: | |
| Propeller Type: | |
| Aircraft Flying (Yes or No): | If yes, Number of flight hours: |
| If you have completed an aircraft weighin | ng, please fill out the weights and stations listed below. |
| WEIGHT | STATION - |
| Right Main: Left Main: Nose Wheel: | (-) |
| Please list below any options/items that system, Ballistic chute, Gyros, ect) | you have installed on your aircraft (Avionics, Vacuum |
| | |
| | |
| | |
| | |
| Places mail this Survey to SkyStar Aircra | oft Corporation, Attn: SL# 54 Survey, 3901 Aviation Way |

Please mail this Survey to SkyStar Aircraft Corporation, Attn: SL# 54 Survey, 3901 Aviation Way, Caldwell, ID 83605.